

**Corrections to the draft report from the ISO/TC 43/SC 1 meeting, 2008-05-29/30 in Borås, Sweden, doc. 43/1 N 1749**

**Item 8.2, third para, 1st sentence (concerning CD 10302-2)**

We have from Standards Norway received the following correction:

The Norwegian delegation had objected to the way of using a mounting plate. However, the convenor of WG 22, Mr Hübner, Germany, explained that WG 22 is working on a general document for a reception plate method, which is based on a thin plate, but CD 10302-2 is a machine specific application and this seemed acceptable.

To be changed to:

".. the way of specifying the mounting plate..."

**Item 9.3.1, first para (concerning review of ISO 5136)**

It has come to the attention of the secretariat that the following clarification should be made:

The secretariat informed that it had received a request from TC 117 "Industrial fans" to give the responsibility for ISO 5136 over to this committee. TC 117 actually also had the same suggestion for ISO 10302. TC 117 feels that the subjects of ISO 10302 and ISO 5136 are so close to the interests of fan manufacturers that it would be appropriate to have them numbered in the ISO 13347 series of standards on "Industrial fans – Determination of fan sound power levels under standardized laboratory conditions".

To be changed to:

The secretariat informed that it had received a request from TC 117 "Industrial fans" stating that TC 117 feels that the subjects of ISO 10302 and ISO 5136 are so close to the interests of fan manufacturers that it would be appropriate to have them numbered in the ISO 13347 series of standards on "Industrial fans – Determination of fan sound power levels under standardized laboratory conditions", prepared by TC 117.

**Item 11.7 (concerning report from WG 33)**

We have from the convenor of WG 33 received the following correction:

"As explained in the written report, the main problem was the choice of the reference tyre for which there were only few candidates left. In accordance with the explanation it was decided to split PWI 11819-2 into two: Part 2 (SPX method) to become an International Standard..."

To be changed to:

"... to split PWI 11819-2 into two: Part 2 (CPX method) to become an International Standard..."

**Item 11.10 (concerning report from WG 40)**

We have from the representative of the ISO Central Secretariat received the following correction:

"On behalf of the convenor Mr White, USA, Mr van der Weele, Netherlands, referred to the additional report given in Annex A to doc. 43/1 N 1739. He explained that WG 40 at its meeting in Borås had dealt with the comments, which had already been received on DIS 13474. The working group was behind schedule – mainly due to computer crash – but he expected that it would be possible to finalize the text for an FDIS before the end of the year."

To be changed to:

"... – but he expected that the text for an FDIS would be ready in November."